



355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

August 9, 1985

TO:

The Board of Oil, Gas and Mining

Lowell P. Braxton, Administrator THRU:

Susan C. Linner, Reclamation Biologist/Permit Supervisor FROM:

RE: Executive Summary, Western Clay Company, Modification to

Redmond Bentonite Pit permit, ACT/041/012,

Sevier County, Utah

Attached for your information is an Executive Summary for Western Clay Company's Redmond Bentonite Pit. Public notice has been given and the 30-day public comment period will end September 1, 1985.

The Division recommends that you concur with the \$8,300 bond amount, to be held by Division of State Lands and Forestry.

jvb 0060R-33

EXECUTIVE SUMMARY

Mine Name: Redmond Bentonite Pit	I. D. No.: ACT/041/012
Operator: Western Clay Company	County: Sevier
P. O. Box 1067	New/Existing: Modification to
Aurora, Utah 84620	Existing mine plan
	Mineral Ownership: State of Utah
Telephone: 801-529-3286	Surface Ownership: State of Utah
Contact Person: Mr. Thomas Chivers	Lease No.(s): ML-1937(State)
Life of Mine: 25Years	Permit Term: 5 years
Legal Description: Section 2, Township 21 S. F	Range 1 West
Mineral(s) to be Mined: Bentonite	
Mining Methods: Open Pit	
Acres to be Disturbed: 8.5 Acres	
Present Land Use: Mining, Grazing	
Postmining Land Use: Grazing	
Variances from Reclamation Standards (Rule M-10)	Granted: None Requested
Soils and Geology:	
Soil Description: Sandy clay loam - clay, the alluvial fans and low lake terrace, alkaline, poph: Colorado Plateau Province Ave. 8.1-9.1 Special Handling Problems: Extremely high sodi Geology Description: Bentonite is found in voldissected by main drainages. Local folding caus	ium content Lcanics near Redmond. High Plateaus
formations and giving rise to hogbacks.	
Hydrology:	
Ground Water Description:	N/A
Surface Water Description: Runoff from the are	ea resulting from the 8 inches of
annual precipitation could enter the Piute Cana	and eventually the Sevier River.
All drainage from the disturbed area is contained	ed locally in pits and ponds where it
evaporates.	
Water Monitoring Plan: N/A	

Page 2 Executive Summary ACT/041/012

Ecology:

Vegetation Type(s);	Dominan	it Species:	Salt	Desert	Shrub	, Shadsacle	e, Snake	eweed,
Sand dropseed, India	an Riceg	rass				141-67		
Percent Surrounding			15%					
Wildlife Concerns:	None.	Area is con	nsidered	to hav	e bee	n overgraze	ed.	
Surface Facilities:	Open	pit and pond	ds. All	raw pr	roduct	is hauled	to Auro	ora for
processing.								
Mining and Reclamati	on Plan	Summary:	Test pla	ots are	e in p	lace to det	termine	the
most feasible techni	ques.	Fencing has	been/wi	ll be c	done t	o mitigate	safety	hazard.
See attached.								
			A.					

Surety:

Amount: \$8,300 Form:

Renewable Term: 5years (1990 dollars)

0352R-7

OPERATION AND RECLAMATION PLAN

During Operations:

- 1. The bentonite clay deposit being mined occurs on the surface and thus does not require explosives to mine. It sometimes requires ripping. The clay is mined with a front-end loader and loaded into a truck for transport to a processing plant in Aurora, Utah
- 2. There will be no structures on site.
- 3. Any topsoil or overburden present will be removed for reclamation purposes.
- 4. Runoff from the minesite will be contained in two catch basins. Any water collecting in the pit will be pumped so as to flow into the catch basins.

Following operations:

- 1. All trash and debris will be cleaned up.
- 2. Slopes will be regraded to a stable configuration.
- 3. Soil material will be reapplied, harrowed and drill seeded with a mixture adapted to the area.
- 4. Test plots have been implemented to help determine the best methods for successful reclamation.